



Rate of Utah

DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director MARY ANN WRIGHT Acting Division Director



Inspection Report Minerals Regulatory Program Report Date: February 14, 2005

Mine Name: Iron Mountain	Permit number: M/021/008			
Operator or Permittee Name:	Inspection Date: Feb. 1, 2005			
Geneva Steel				
Permittee Mailing Address:				
P.O. Box 2500				
RFD 1				
Provo, Utah				
	Weather: Cool, cloudy			
Inspector(s): Doug Jensen	Inspecti	Inspection Start Time: 8:45 AM		
	Inspecti	ion End Tim	e: 9:15 AM	
Other Participants: None	Site location/Area Inspected (i.e. Pit #):			
		ck/Mtn Lion		
Permit Status: Inactive	Surface Ownership: BLM/Fee			
Current Acreages:	Mineral Ownership: Mixed			
Total Permitted (Bonded): 417	Mineral Mined: Hematite/Magnetite			
Total Disturbed: ???	Type of Mine: Open Pit			
Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	7	\boxtimes		
2. Public Safety (open shafts, adits, trash,				
signs, highwalls)				
3. Protection of Drainages				
4. Explosives, magazines				
5. Deleterious Material		\bowtie		
6. Roads (maintenance, surfacing, dust control,				
safety)				
7. Concurrent Reclamation				
8. Erosion Control		\boxtimes		
9. Demolition		\boxtimes		
10. Backfilling and Grading (trenches, pits,		\boxtimes		
roads, highwalls, shafts, drill holes)				
11. Water Impoundments	\sqcup	\boxtimes		
12. Soils		×		
13. Revegetation		×		
14. Air Quality				
15. Facilities				
16 Other				

Inspection Date: Feb 1, 2005; Report Date: Feb 14, 2005

Page 2 of 2 M/021/008

Purpose of Inspection:

To check the site prior to Board tour to assess the road conditions and see if gates into the site were open.

Inspection Summary:

I entered into the site on the lower road leading to the Comstock/Mtn Lion Pit area. There were several inches of snow on the road. Tracks on the road indicated that there had been traffic into this site before my visit. The gate across the road was open and the road was in good shape, considering how long it has been since any maintenance has been done on it.

I inspected the shop/plant area near the pit, there has been quite a bit of vandalism to these buildings. It was obvious that vandalism at the site was a problem at the time of my last inspection of the site in 1999 and is still ongoing. This is probably due to the fact that Geneva has gone into bankruptcy and there is no longer a part-time watchman at the site. The proximity to the highway and Cedar City probably contributes to the vandalism problem.

If no more snow falls between now and the February 22 Board visit to the site, access into the site should be open. Much of what the Board will want to see could possibly be at least partially snow covered.

Directions to the site:

The site is located approximately 15 miles west of Cedar City

GPS data:

None gathered

Inspector's Signature 🗸

Date: Feb 14, 2005

DJ:jb

cc:

Richard Ross, Geneva Steel, Operator Ed Ginouves, BLM Cedar City FO

O:\M021-Iron\M0210008-IronMtn\inspections\02012005ins.doc